


# OVERALL UNIT COMPLIANCE WITH ALL MEASURES

■ % Met ■ % Unmet/Blank




## Compliance by Equipment Group & Total

	Unit	SMH	BAS	BOU	DCH	MKU	RBH	SAL	Poole	UHS	WIN	WPH	IOW	OUH	QAH	SCAS V*	SCAS B*
Advanced Airway Equipment	% Met	100%	100%	89%	79%	100%	79%	95%	95%	95%	95%	100%	100%	84%	100%	100%	100%
	% Unmet/Blank	0%	0%	11%	21%	0%	21%	5%	5%	5%	5%	0%	0%	16%	0%	0%	0%
Breathing Equipment	% Met	100%	91%	100%	91%	100%	82%	100%	100%	100%	82%	64%	100%	82%	100%	91%	91%
	% Unmet/Blank	0%	9%	0%	9%	0%	18%	0%	0%	0%	18%	36%	0%	18%	0%	9%	9%
Self-ventilating Equipment	% Met	75%	88%	88%	88%	75%	100%	100%	100%	88%	88%	63%	100%	100%	100%	100%	100%
	% Unmet/Blank	25%	13%	13%	13%	25%	0%	0%	0%	13%	13%	38%	0%	0%	0%	0%	0%
Suction Equipment	% Met	100%	100%	100%	100%	100%	80%	100%	100%	80%	100%	100%	100%	80%	100%	100%	100%
	% Unmet/Blank	0%	0%	0%	0%	0%	20%	0%	0%	20%	0%	0%	0%	20%	0%	0%	0%
Circulation Equipment	% Met	95%	95%	95%	91%	100%	68%	100%	91%	73%	91%	77%	100%	68%	100%	100%	100%
	% Unmet/Blank	5%	5%	5%	9%	0%	32%	0%	9%	27%	9%	23%	0%	32%	0%	0%	0%
External Equipment	% Met	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%
	% Unmet/Blank	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%
Inside pouch on side of bag	% Met	80%	80%	60%	60%	100%	20%	40%	100%	40%	80%	20%	80%	0%	100%	100%	100%
	% Unmet/Blank	20%	20%	40%	40%	0%	80%	60%	0%	60%	20%	80%	20%	100%	0%	0%	0%
Interventional circulation Equipment	% Met	71%	29%	71%	29%	86%	43%	100%	71%	57%	29%	43%	100%	100%	100%	100%	100%
	% Unmet/Blank	29%	71%	29%	71%	14%	57%	0%	29%	43%	71%	57%	0%	0%	0%	0%	0%
Total	% Met	92%	88%	90%	81%	96%	72%	95%	94%	81%	85%	74%	99%	77%	100%	99%	99%
	% Unmet/Blank	8%	12%	10%	19%	4%	28%	5%	6%	19%	15%	26%	1%	23%	0%	1%	1%


\*SCAS V - SCAS North Vehicle

\*SCAS B - SCAS North Bag


### Advanced Airway Equipment Compliance




### Breathing Equipment Compliance




### Self-ventilating Equipment Compliance




### Suction Equipment Compliance




### Circulation Equipment Compliance




### External Equipment Compliance



### Inside pouch on side of bag Compliance



### Interventional circulation Equipment Compliance









<b>4. 5 x Needles Blue</b>																
<b>5. 5 x Needles White</b>																
<b>6. 5 x Drawing up needles</b>																
<b>7. 2 x Tourniquets</b>																

\*SCAS V - SCAS North Vehicle

\*SCAS B - SCAS North Bag